NOTE: WATER ELEVATIONS OBSERVED ON 09/05/25.

PROPOSED WORK AREA

EXISTING RCP DRAINAGE PIPE
EXISTING GRATE INLET

EXISTING CONTROL STRUCTURE

EXISTING ENDWALL

NOTE:
IF CLEARING AND DEBRIS REMOVAL OF
DITCH DOES NOT RELIEVE THE
SLOW-DRAINAGE CONDITIONS AT FALLING
LEAF COURT, THE PIPING BETWEEN THE
NOTED INLET AND POND 12, BETWEEN POND
12 AND POND 13, AND BETWEEN POND 13
AND THE OUTFALL DITCH WILL BE FLUSHED.

SILVERLEAF COMMUNITY DEVELOPMENT DISTRICT

SHEET NUMBER

10F1